BUKTI KORESPONDENSI

ARTIKEL JURNAL NASIONAL BEREPUTASI

Judul Artikel : Study of water quality for post-mining extermination, Banjarbaru City

Jurnal : DEPIK Jurnal Ilmu-Ilmu Perairan, Pesisir dan Perikanan, 2023, Volume 12 (3): 409 -414

Penulis : Dini Sofarini (*coresponding author*), Reza Agustian, Yunandar, Rina Nur Hidayah

No.	Perihal	Tanggal
1.	Bukti konfirmasi submit artikel dan artikel yang disubmit	3 Juli 2023
2.	Bukti konfirmasi review dan hasil review pertama	8 Sept 2023
3.	Bukti konfirmasi submit revisi pertama, respon kepada reviewer, dan artikel yang diresubmit	18 Sept 2023
4.	Bukti konfirmasi artikel accepted	23 Sept 2023
5.	Bukti konfirmasi artikel published online	27 Des 2023

1.Bukti Konfirmasi Submit Artikel
dan Artikel yang Disubmit
(3 Juli 2023)

Home | About | User Home | Categories | Search | Current | Archives | Announcements | Copyright

Home > User > Author > Submissions > #32909 > **Summary**

SUMMARY   REVIEW   EDITING

Submission

Authors	Dini Sofarini, Reza Agustian, Yunandar Yunandar, Rina Nur Hidayah
Title	Study of water quality for post-mining extermination, Banjarbaru City
Original file	32909-109793-1-SM.DOCX 2023-07-03
Supp. files	None
Submitter	Dr. Dini Sofarini ✉
Date submitted	July 3, 2023 - 05:33 AM
Section	Articles
Editor	Ichsan Setiawan ✉
Author comments	please send me by my email too, besides my OJS account, for the reviewing my manuscript
Abstract Views	0

ABOUT THE JOURNAL:

Aims and Scope

Editorial Team

Reviewer Team

FOR AUTHORS:

Guideline for Author

STUDY OF WATER QUALITY FOR POST-MINING EXTERMINATION, BANJARBARU CITY

Dini Sofarini[1,*], Reza Agustian[2], Yunandar[1], Rina Nur Hidayah[1]

[1] Department of Aquatic Resource Management, Faculty of Fisheries and Marine, Universitas Lambung Mangkurat, Indonesia.
[2] Geoenviro Environmental Laboratory, Indonesia.

ABSTRACT

Banjarbaru City is one of the regencies/cities in South Kalimantan Province which continues to develop in various sectors, one of which is mining. Among the mining areas that left traces of voids in Banjarbaru include the Lake Seran quarry which was once a sand mining site, as well as the Pumpung quarry which was a diamond mining location. Remains of former mining excavations that are left for a long time will be filled with water which accumulates various substances remaining at the excavation site, especially heavy metals which in general are important parameters and affect water quality. This study aims to examine the quality of ex-mine water in Banjarbaru by focusing on analysis through the Pollution Index (IP) of heavy metal parameters in the waters of the research location. The results obtained are that the ex-mine pits in Lake Seran and Pumpung, Banjarbaru City, have quite good water quality, where most of them are at class 2 quality standards. However, further management is needed to improve water quality at some points that are still not meets class 2 quality standards so that it is included in the category of lightly polluted.

Introduction

Mining activities have a very important function in supporting economic activities in Indonesia, including South Kalimantan. Apart from contributing a sizable amount of foreign exchange, mining activities are also able to absorb a large number of workers and create centers of economic growth and new settlements.

In addition to providing great benefits, mining activities also cause problems in environmental management. Some of these problems include the occurrence of water pollution, land degradation, decreased biodiversity (Goswami, 2015; Salomons, 1995; Setiawan et al., 2018; Younger, 2004), land conflict (Dutu, 2016; Hudayana *et al.*, 2020), and in certain cases there has been a breakdown of settling ponds and the drowning of several victims (people) in inactive post-mining pits filled with water called coal mine pit lakes or post-mining pits. (Yunus and Prabowo, 2023)

Mining activities have a great impact on the ecosystem around the mining site, one of which is the aquatic ecosystem (artificial lakes). Changes in water quality will definitely occur due to changes in the landscape, which means it will affect the life of living things in it (McCullough and van Etten, 2011; Sofarini, 2011)

In general, post-mining pits will fill with water and accumulate various parameters of heavy metals such as Pb, Hg, Cd, Fe and others (Wahlberg, 2002; Xu *et al.*, 2021). The presence of these heavy metals will disrupt the stability of the ecosystem if not taken seriously. According to Dinora and Purnomo (2013), Fe is a type of heavy metal that can be found in almost all of the earth's surface in all geological layers and waters. In natural water systems and also in water treatment systems, iron compounds can vary depending on the pH of the water.

* Corresponding author.
Email address: xxxxxx@xxxx

Post-mining land that has been damaged in its management must prioritize improving its biophysical or ecological conditions, with the results of the analysis in this study being post-mining land management based on sustainable development (Haridjaja *et al.*, 2011; Kodir *et al.*, 2017). The presence of post-mining pits that have not been closed or not closed indicates problems both from the aspect of scenarios for exploitation and operational activities for closing post-mining pits, weak instruments in mining environmental management, and the resulting environmental impacts (Adibi *et al.*, 2015; Asr *et al.*, 2019; Jaelani *et al.*, 2022).

These various problems are an increasing challenge, considering the need for better environmental management while the number of post-mining is increasing (Absori et al., 2021). This study seeks to photograph the problems of post-mining pits and see opportunities for the utilization of post-mining pits from various aspects of utilization and regulatory needs. The results of this study are expected to be useful as a reference for formulating operational policies in the utilization of post-mining pits in mining activities in South Kalimantan

Materials and Methods
Location and time of research
This research was carried out for 4 months from June to October 2022. The research was carried out in ex-mining pits in Lake Seran and Pumpung which are located in Banjarbaru City, South Kalimantan Province (Figure 1 and Figure 2). Determining the location of water sampling was carried out by purposive sampling. The method used is explorative quantitative

Data collection procedure
Analysis of water quality parameters refers to the Indonesian national standard (SNI) according to SNI 6989.59:2008 and 6989.57:2008 as much as 5 liters using a water sampler and sampling container. Then the samples were brought to the laboratory for analysis of the physical and chemical parameters of the water. The instrument used has previously been tested for calibration

Data analysis
The data obtained was then analyzed using the Pollution Index (PI) method according to the Decree of the State Minister for the Environment Number 115 of 2003 concerning Guidelines for Determining Water Quality Status with class 2 quality standard criteria. The PI calculation is carried out based on the following equation:

$$PI_j = \sqrt{\frac{(C_i/L_{ij})M^2 + (C_i/L_{ij})R^2}{2}}$$

Information :
PI_j = Pollution Index for designation (j)
C_i = Concentration of water quality parameters (i) obtained from the analysis results water sample at a location taking
L_{ij} = Concentration of water quality parameters listed in the Quality Standards Water Designation (j)

$(C_i/L_{ij})M$ = maxium value of C_i/L_{ij}
$(C_i/L_{ij})R$ = average value of C_i/L_{ij}

The results of the calculations obtained will be interpreted with the following evaluation:

$0 \leq PI_j \leq 1.0$ → meets the quality standard (good condition)
$1.0 < PI_j \leq 5.0$ → lightly polluted
$5.0 < PI_j \leq 10$ → moderately polluted
$PI_j > 10$ → heavily polluted

Figure 1. The location of Danau Seran Post-Mining

Figure 2. The location of Pumpung Post-Mining

Results
The concentrations of heavy metals measured at each observation station diverse, some are varied and some are not so much different concentrations.

Table 1. Data results of water sample measurements at Danau Seran

Parameters	Unit	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
Fe	Mg/L	0.3	0.3	0.40	0.3	0.3	0.3
Mn	Mg/L	0.34	0.23	0.41	0.25	0.25	0.26
Zn	Mg/L	0.688	0.165	0.162	0.148	0.082	0.071
Pb	Mg/L	0.03	0.03	0.03	0.03	0.03	0.03
As	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Co	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Se	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cd	Mg/L	0.004	0.004	0.004	0.004	0.004	0.004
Cu	Mg/L	0.008	0.008	0.008	0.008	0.008	0.008
Hg	Mg/L	0.075	0.075	0.075	0.075	0.075	0.075
Ni	Mg/L	0.044	0.044	0.044	0.044	0.044	0.044
B	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cr Total	Mg/L	0.015	0.015	0.015	0.015	0.015	0.015

Source : Primary Data, 2022

Table 2. Data results of water sample measurements at Pumpung

Parameter	Unit	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
Fe	Mg/L	0.86	0.63	0.42	0.3	0.43	0.33
Mn	Mg/L	0.16	0.16	0.19	0.1	0,1	0.11
Zn	Mg/L	0.111	0.075	0.090	0,05	0.051	0.05
Pb	Mg/L	0.03	0.03	0.03	0.03	0.03	0.03
As	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Co	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Se	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cd	Mg/L	0.004	0.004	0.004	0.004	0.004	0.004
Cu	Mg/L	0.013	0.010	0.010	0.010	0.010	0.010
Hg	Mg/L	0.075	0.075	0.075	0.075	0.075	0.075
Ni	Mg/L	0.044	0.044	0.044	0.044	0.044	0.044
B	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cr Total	Mg/L	0.018	0.015	0.015	0.015	0.015	0.015

Source : Primary Data, 2022

After performing calculations with the PI equation, the following results are obtained:

Table 3. Pollution Index Calculation Results at Danau Seran

Danau Seran	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
(Ci/Lij)R	1.62	0.91	1.10	0.96	0.96	1.00
(Ci/Lij)M	8.87	1.00	2.26	1.00	1.00	1.09
Pi	4.508	0.676	1.255	0.693	0.694	0.736
Quality Status	Lightly Pollution	Meet Quality Standards	Lightly Pollution	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards

Table 4. Pollution Index Calculation Results at Pumpung

Pumpung	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
(Ci/Lij)R	1.28	0.94	1.06	0.92	1.00	1.02
(Ci/Lij)M	8.87	1.00	1.40	1.00	1.04	1.21
Pi	4.481	0.686	0.878	0.681	0.724	0.789
Quality Status	Lightly Pollution	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards

Source : Processed primary data

Discussion

Based on the results of the data above, it can be seen that the post-mining pit Danau Seran, Banjarbaru City, generally meets the Quality Standards for class 2 designation. This means that these waters could be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water to irrigate crops and for other uses that require the same quality of water as those uses. However, at station 1 and station 3, the Pollution Index (PI) results were obtained at 4.508 and 1.255, which means that these locations were indicated to be lightly polluted, so further management of the measured parameters was needed so that the water quality at that point could be appropriate. with the need for predetermined water quality standards (Widiatmaka, et al., 2010; Wikurendra, et al., 2022).

The development of Danau Seran tourism was originally intended to develop the region and create new growth in the area. Utilization of post-diamond mining land PT. Galuh Cempaka, among other things, was to create new public spaces, encourage the growth of small and medium enterprises, create new jobs, develop tourism objects, and open up regional sources of income. From various aspects of the utilization of Danau Seran, no review was carried out from the side of water quality. The problem of changing the landscape will further impact on the water quality of Seran Lake (Munir and Setyowati, 2017; Novianti et al., 2017).

Numbers of rivers around Seran Lake were experiencing a lot of siltation caused by silt sedimentation from mining activities. This clearly causes the potential for flooding which can occur at any time, but from a micro perspective this can be overcome by improving the quality and performance of the inlet and outlet handles in the Galuh Cempaka Site, where Danau Seran was located on peat soil.

In the post-mining waters in Pumpung, Banjarbaru City, it can be seen that these waters

generally meet the Quality Standards for class 2 designations where these waters can be used for

water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water for irrigating crops and for other uses that require the same quality of water as those uses. However, at station 1, the results of the Pollution Index (PI) figure were 4.481, which means that the location was indicated to be lightly polluted, so further management of the measured parameters was needed so that the water quality at that point coud meet the needs of water quality standards established (Kirschke et al., 2020).

In contrast to the Danau Seran post-mining, the Pumpung area is a community's traditional post-diamond mining. Pumpung Village is famous for finding a diamond for the size of a chicken egg weighing 166.7 pieces, in the 30s years ago which was known as the Trisakti.

The diamond mining system in Pumpung Village uses a dumping system, namely a method of mining by stripping the surface soil and then continuing with excavation, but after mining was complete, the top soil layer was not returned to its original place. Physically, the condition of the former mining site was very bad, from large holes like lakes and surrounded by heaps of excavated earth like small irregular hills. Under these conditions, the utilization of the post-mining area as agricultural land was very difficult to manage. Returning the quality of former mining areas as agricultural land requires a very large investment, which was actually the responsibility of the miners (Barkatullah and Abdullah, 2016)

Mining activities that do not pay attention to environmental aspects from erosion and landslide hazards as loss of ground cover vegetation. Land clearing on a large scale causes a landscape (morphology and topography), namely a change in the shape of the slope. Stripping, stockpiling of overburden from diamond mining activities causes changes in drainage, river water discharge and surface quality when it rains (Andriawan, et al., 2021).

Based on water quality data for Danau Seran and Pumpung, several heavy metals such as Fe, Zn, and Hg had values that exceed the required water quality standards. Heavy metal pollution from mining activities can cause changes in the quality of the aquatic environment, one of which is post-mining land (Islam, et al., 2015) and affects the life of the biota in it (Barbieri et al., 2020; Fuoco and Giannarelli 2019; Kurz et al., 2013) . Continuous pollution can have an impact on biota and even cause death to impact the population (Kadim et al., 2022).

The heavy metal parameters that had the most influence on the Pollution Index results obtained include Fe, Zn and Hg, which can disturb the environment. Even though Fe and Zn are essential heavy metal groups, if they are present in excessive amounts they are toxic to living things (Febrina and Ayuna, 2015; Kamarati et al., 2018; Said and Yudo, 2021).

The presence of iron can be affected by acidic water conditions. Mining land of diamonds in Danau Seran and Pumpung were pyrite (FeS_2). The mineral pyrite (FeS_2), in post-coal mining land, is oxidized to sulfuric acid and can drastically reduce soil pH. Meanwhile carbonate ($Ca/MgCO_3$) which coats minerals and rocks tends to increase soil pH due to weathering and dissolving. In post-mining land where the carbonate is not weathered it causes a greater accumulation of pyrite, so that the pH can fall quickly (Erfandi, 2017; Hirfan, 2016; Supriyatna et al., 2013)

While the main role of zinc in waters is as a cofactor for two important enzymes for the development of phytoplankton, namely carbonic anhydrase and alkaline phosphatase. Apart from being essential, zinc can also be toxic and generally zinc is toxic when it is in the dissolved phase (Ali et al., 2018)

The presence of Hg as part of non-essential heavy metals will be toxic to organisms in the waters. High Hg levels, both in Danau Seran and Pumpung, would be toxic and the benefits for the aquatic organisms that live in them were not yet known. Metabolic processes in living bodies will be interrupted due to toxic forces that will work as a barrier to the work of enzymes in the body (Kadim et al., 2022; Said and Yudo, 2021; Sofarini et al., 2022).

Based on data on several heavy metals which were quite high in Danau Seran and Pumpung, it will have a further impact on the Pollution Index which was classified as lightly polluted at Stations 1 and 3. However, despite the problems found, Danau Seran and Pumpung still have considerable potential for developed. This of course has to go through several processes and stages, especially post-mining land reclamation.

Reclamation activities are the end of mining activities which are expected to return land to its original state, even if possible, to be better than conditions before mining. The ultimate goal of reclamation is to restore post-mining land to be safe, stable and not easily eroded so that, it can be utilized back (Hirfan, 2016). In general, the outline of the reclamation stages are top soil conservation, land management, sediment management and erosion control, planting cover crops, planting

pioneer plants, and controlling heavy metals through the concepts of phytoremediation or bioremediation (Hendrychov´a *et al.,* 2020; Hirfan, 2016) .

Conclusion

The post-mining pits in Danau Seran and Pumpung, Banjarbaru City, have quite good water quality, most of which were at class 2 quality standards. These waters could be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water for irrigation. plantations and for other uses that require the same quality of water as that use. However, further management was needed to improve water quality at some points which still did not meet class 2 quality standards so that they were included in the lightly polluted category.

Acknowledgments

References

Absori, Absori, Aulia Vivi Yulianingrum, Khudzaifah Dimyati, Harun Harun, Arief Budiono, Hari Sutra Disemadi . 2021. "Environmental Health-Based Post-Coal Mine Policy in East Borneo." Open Access Macedonian Journal of Medical Sciences 9: 740–44.

Adibi, Nabiollah, Majid Ataee-Pour, and Mehdi Rahmanpour. 2015. "Integration of Sustainable Development Concepts in Open Pit Mine Design." Journal of Cleaner Production 108: 1037–49. http://dx.doi.org/10.1016/j.jclepro.2015.07.150.

Ali, Attarad, Abdul-rehman Phull, and Muhammad Zia. 2018. "Elemental Zinc to Zinc Nanoparticles : Is ZnO NPs Crucial for Life ? Synthesis , Toxicological , and Environmental Concerns." Nanotechnol Review 7(5): 413–41.

Andriawan, Feri, Muhammad Akib, and Agus Triono. 2021. "Pengendalian Kerusakan Lingkungan Akibat Aktivitas Pertambangan Di Kecamatan Pasir Sakti (Environmental Damage Control Due to Mining Activities in Pasir Sakti District)." Jurnal Ilmiah Hukum dan Hak Asasi Manusia 1(1): 1–10.

Asr, Elmira Tajvidi, Reza Kakaie, Mohammad Ataei, and Mohammad Reza Tavakoli Mohammadi. 2019. "A Review of Studies on Sustainable Development in Mining Life Cycle." Journal of Cleaner Production 229: 213–31. https://doi.org/10.1016/j.jclepro.2019.05.029.

Barbieri, Maria Vittoria et al. 2020. Environmental Pollution Jo Ur l P Re Of. Elsevier Ltd. https://doi.org/10.1016/j.envpol.2020.115813

Barkatullah, Abdul Halim, and Dadang Abdullah. 2016. "Tanggung Jawab Pemerintah Dalam Menjaga Kualitas Lingkungan Di Wilayah Penambangan Intan Tradisional Cempaka." Al'Adi VIII(3): 1–22.

Dinora, G.Q; Purnomo, A. 2013. "Penurunan Kandungan Zat Kapur Dalam Air Tanah Dengan Menggunakan Media Zeolit Alam Dan Karbon Aktif Menjadi Air Bersih." Jurnal Teknik Pomits 2(2): D78–82.

Dutu, Richard. 2016. "Challenges and Policies in Indonesia's Energy Sector." Energy Policy 98: 513–19. http://dx.doi.org/10.1016/j.enpol.2016.09.009

Erfandi, Deddy. 2017. "Pengelolaan Lansekap Lahan Bekas Tambang: Pemulihan Lahan Dengan Pemanfaatan Sumberdaya Lokal (In-Situ)." Jurnal Sumberdaya Lahan 11(2): 55–66.

Febrina, Leila, and Astrid Ayuna. 2015. "Studi Penurunan Kadar Besi (Fe) Dan Mangan (Mn) Dalam Air Tanah Menggunakan Saringan Keramik." Teknologi 7(1): 35–44.

Fuoco, Roger, and Stefania Giannarelli. 2019. "Integrity of Aquatic Ecosystems : An Overview of a Message from the South Pole on the Level of Persistent Organic Pollutants (POPs) ☆." Microchemical Journal 148(February): 230–39. https://doi.org/10.1016/j.microc.2019.04.076.

Goswami, Sribas. 2015. "Impact of Coal Mining on Environment." European Researcher 92(3): 185–96.

Haridjaja, Oteng, Wiwik Dwi Haryanti, and Rina Oktaviani. 2011. "Perencanaan Pengelolaan Sumberdaya Lahan Yang Terkena Dampak Penggunaan Lahan Untuk Penambangan Kapur." Jurnal Ilmu Pertanian Indonesia 16(1): 35–42.

Hendrychov´a, Mark´eta, Kamila Svobodova, and Martin Kabrna. 2020. "Mine Reclamation Planning and Management : Integrating Natural Habitats into Post-Mining Land Use." Resources Policy 69(September): 1–13.

Hirfan. 2016. "Strategi Reklamasi Lahan Pasca Tambang." Pena Teknik 1(1): 101–8.

Hudayana, Bambang, Suharko, and A. B. Widyanta. 2020. "Communal Violence as a Strategy for Negotiation: Community Responses to Nickel Mining Industry in Central Sulawesi, Indonesia." Extractive Industries and Society 7(4): 1547–56. https://doi.org/10.1016/j.exis.2020.08.012.

Islam, Saiful, Kawser Ahmed, and Mohammad Raknuzzaman. 2015. "Heavy Metal Pollution in Surface Water and Sediment : A Preliminary Assessment of an Urban River in a Developing Country." Ecological Indicators 48: 282–91. http://dx.doi.org/10.1016/j.ecolind.2014.08.016.

Kadim, Miftahul Khair et al. 2022. "Distribution of Heavy Metal (Pb, Cd and Hg) Concentrations in Sediment of Bone River, Gorontalo." Depik 11(3): 282–87.

Kadir Jaelani, Abdul, Reza Octavia Kusumaningtyas, and Asron Orsantinutsakul. 2022. "The Model of Mining Environment Restoration Regulation Based on Sustainable Development Goals." Legality : Jurnal Ilmiah Hukum 30(1): 131–46.

Kamarati, Kiamah Fathirizki A et al. 2018. "Kandungan Logam Berat Besi (Fe), Timbal (Pb) dan Mangan (Mn) pada Air Sungai Santan." Jurnal Penelitian Ekosistem Dipteropkarya 4(1): 49–56.

Kirschke, Sabrina et al. 2020. "Capacity Challenges in Water Quality Monitoring: Understanding the Role of Human Development." Environmental Monitoring and Assessment 192(5).

Kodir, Abdul, Djoko M. Hartono, Herman Haeruman, and Irdika Mansur. 2017. "Integrated Post Mining Landscape for Sustainable Land Use: A Case Study in South Sumatera, Indonesia." Sustainable Environment Research 27(4): 203–13. http://dx.doi.org/10.1016/j.serj.2017.03.003.

Kurz, Marie J et al. 2013. "Controls on Diel Metal Cycles in a Biologically Productive Carbonate-Dominated River." Chemical Geology 358: 61–74. http://dx.doi.org/10.1016/j.chemgeo.2013.08.042.

McCullough, Clint D., and Eddie J.B. van Etten. 2011. "Ecological Restoration of Novel Lake Districts: New Approaches for New Landscapes." Mine Water and the Environment 30(4): 312–19.

Munir, Misbakhul, and R.R.Dyah Nugrahaeni Setyowati. 2017."Kajian Reklamasi Lahan Pasca Tambang Di Jambi, Bangka, Dan Kalimantan Selatan." KLOROFIL 1(1): 11–16.

Novianti, Yuniar Siska et al. 2017. "Kajian Kualitas Air Pada Danau Bekas Tambang Di Kota Banjarbaru Provinsi Kalimantan Selatan." Prosiding Seminar Nasional Riset Terapan 5662(November): 70–77.

Said, Nusa Idaman, and Satmoko Yudo. 2021. "Status Kualitas Air Di Kolam Bekas Tambang Batubara Tambang Stui, Kabupaten Tanah Laut, Kalimantan Selatan." Teknologi Lingkungan 22(1): 048–057.

Salomons, W. 1995. "Environmental Impact of Metals Derived from Mining Activities: Processes, Predictions, Prevention." Journal of Geochemical Exploration 52(1–2): 5–23.

Setiawan, Andi Arif, Dedik Budianta, Suheryanto Suheryanto, and Dwi Putro Priadi. 2018. "Review : Pollution Due to Coal Mining Activity and Its Impact on Environment." Sriwijaya Journal of Environment 3(1): 1–5.

Sofarini, Dini. 2011. "Karakteristik Fisik-Kimia Kualitas Air Pada Lahan Bekas Tambang Bahan Galian Golongan c Di Kecamatan Landasan Ulin Kota Banjarbaru." EnviroScienteae 7: 6–11.

Sofarini, Dini, Suhaili Asmawi, Rina Nur Hidayah, and Guinever Castle Angela Mangalik. 2022. "Heavy Metal Residue on Water, Biota and Sediment in Negara River." Russian Journal of Agricultural and Socio-economic Sciences 10(130): 101–8.

Supriyatna, Ateng, R.D Ramdani, and Dede Suhendar. 2013. "Korelasi Kandungan Besi Terlarut Terhadap Kelimpahan Phytoconois Sp Pada Perairan Situ Ciburuy Kabupaten Bandung Barat." Jurnal Sunan Gunung Djati VII(1): 1–18.

Tarras-Wahlberg, N. H. 2002. "Environmental Management of Small-Scale and Artisanal Mining: The Portovelo-Zaruma Goldmining Area, Southern Ecuador." Journal of Environmental Management 65(2): 165–79.

Widiatmaka, Suwarno, and Nandi Kusmaryandi. 2010. "Karakteristik Pedologi Dan Pengelolaan Revegetasi Lahan Bekas Tambang Nikel : Studi Kasus Lahan Bekas Tambang Nikel Pomalaa , Sulawesi Tenggara Pedological Characteristics And Revegetation Management Of Nickel Post Mining Land : Case Study Of Nickel Post." 12(2): 1–10.

Wikurendra, Edza Aria, Achmad Syafiuddin, Globila Nurika, and Alinea Dwi Elisanti. 2022. "Water Quality Analysis of Pucang River, Sidoarjo Regency to Control Water Pollution." Environmental Quality Management 32(1): 133–44.

Xu, Shanshan et al. 2021. "Effects of Vegetation Restoration on Accumulation and Translocation of Heavy Metals in Post-Mining Areas." Land Degradation and Development 32(5): 2000–2012.

Younger, Paul L. 2004. "Environmental Impacts of Coal Mining and Associated Wastes: A Geochemical Perspective." Geological Society Special Publication 236: 169–209.

Yunus, Muhammad; Prabowo, B.A. 2023. "Al-Azhar Islamic Law Review." Al-Azhar Islamic Law Review 5(1): 61–71.

2. Bukti Konfirmasi Review dan Hasil Review Pertama

(8 Sept 2023)

Peer Review

ROUND 1

Review Version	32909-109794-2-RV.DOCX	2023-07-29
Initiated	2023-07-29	
Last modified	2023-09-08	
Uploaded file	Reviewer F 32909-114537-1-RV.DOCX	2023-09-08

DEPIK
Jurnal Ilmu-Ilmu Perairan, Pesisir dan Perikanan

Study of water quality for post-mining extermination, Banjarbaru City

Dini Sofarini[1,*], Reza Agustian[2], Yunandar[1], Rina Nur Hidayah[1]

[1] Department of Aquatic Resource Management, Faculty of Fisheries and Marine, Universitas Lambung Mangkurat, Indonesia.
[2] Geoenviro Environmental Laboratory, Indonesia.

ARTICLE INFO

ABSTRACT

Banjarbaru City is one of the regencies/cities in South Kalimantan Province which continues to develop in various sectors, one of which is mining. Among the mining areas that left traces of voids in Banjarbaru include the Lake Seran quarry which was once a sand mining site, as well as the Pumpung quarry which was a diamond mining location. Remains of former mining excavations that are left for a long time will be filled with water which accumulates various substances remaining at the excavation site, especially heavy metals which in general are important parameters and affect water quality. This study aims to examine the quality of ex-mine water in Banjarbaru by focusing on analysis through the Pollution Index (IP) of heavy metal parameters in the waters of the research location. The results obtained are that the ex-mine pits in Lake Seran and Pumpung, Banjarbaru City, have quite good water quality, where most of them are at class 2 quality standards. However, further management is needed to improve water quality at some points that are still not meets class 2 quality standards so that it is included in the category of lightly polluted.

Introduction

Mining activities have a very important function in supporting economic activities in Indonesia, including South Kalimantan. Apart from contributing a sizable amount of foreign exchange, mining activities are also able to absorb a large number of workers and create centers of economic growth and new settlements.

In addition to providing great benefits, mining activities also cause problems in environmental management. Some of these problems include the occurrence of water pollution, land degradation, decreased biodiversity (Goswami, 2015; Salomons, 1995; Setiawan et al., 2018; Younger, 2004), land conflict (Dutu, 2016; Hudayana et al., 2020), and in certain cases there has been a breakdown of settling ponds and the drowning of several victims (people) in inactive post-mining pits filled with water called coal mine pit lakes or post-mining pits. (Yunus and Prabowo, 2023)

Mining activities have a great impact on the ecosystem around the mining site, one of which is the aquatic ecosystem (artificial lakes). Changes in water quality will definitely occur due to changes in the landscape, which means it will affect the life of living things in it (McCullough and van Etten, 2011; Sofarini, 2011)

In general, post-mining pits will fill with water and accumulate various parameters of heavy metals such as Pb, Hg, Cd, Fe and others (Wahlberg, 2002; Xu et al., 2021). The presence of these heavy metals will disrupt the stability of the ecosystem if not taken seriously. According to Dinora and Purnomo (2013), Fe is a type of heavy metal that can be found in almost all of the earth's surface in all geological layers and waters. In natural water systems and also in water treatment systems, iron compounds can vary depending on the pH of the water.

Post-mining land that has been damaged in its management must prioritize improving its

* Corresponding author.
Email address: xxxxxx@xxxx

biophysical or ecological conditions, with the results

of the analysis in this study being post-mining land management based on sustainable development (Haridjaja *et al.*, 2011; Kodir *et al.*, 2017). The presence of post-mining pits that have not been closed or not closed indicates problems both from the aspect of scenarios for exploitation and operational activities for closing post-mining pits, weak instruments in mining environmental management, and the resulting environmental impacts (Adibi *et al.*, 2015; Asr *et al.*, 2019; Jaelani *et al.*, 2022).

These various problems are an increasing challenge, considering the need for better environmental management while the number of post-mining is increasing (Absori et al., 2021). This study seeks to photograph the problems of post-mining pits and see opportunities for the utilization of post-mining pits from various aspects of utilization and regulatory needs. The results of this study are expected to be useful as a reference for formulating operational policies in the utilization of post-mining pits in mining activities in South Kalimantan

Materials and Methods
Location and time of research
This research was carried out for 4 months from June to October 2022. The research was carried out in ex-mining pits in Lake Seran and Pumpung which are located in Banjarbaru City, South Kalimantan Province (Figure 1 and Figure 2). Determining the location of water sampling was carried out by purposive sampling. The method used is explorative quantitative

Data collection procedure
Analysis of water quality parameters refers to the Indonesian national standard (SNI) according to SNI 6989.59:2008 and 6989.57:2008 as much as 5 liters using a water sampler and sampling container. Then the samples were brought to the laboratory for analysis of the physical and chemical parameters of the water. The instrument used has previously been tested for calibration

Data analysis
The data obtained was then analyzed using the Pollution Index (PI) method according to the Decree of the State Minister for the Environment Number 115 of 2003 concerning Guidelines for Determining Water Quality Status with class 2 quality standard criteria. The PI calculation is carried out based on the

following equation: $\overline{(C_i/L_{ij})^2 + (C_i/L_{ij})^2}$

Information :

PIj = Pollution Index for designation (j)
Ci = Concentration of water quality parameters (i) obtained from the analysis results water sample at a location taking
Lij = Concentration of water quality parameters listed in the Quality Standards Water Designation (j)

Ci/Lij)M = maxium value of Ci/Lij
(Ci/Lij)R = average value of Ci/Lij

The results of the calculations obtained will be interpreted with the following evaluation:

$0 \leq PIj \leq 1.0$ → meets the quality standard (good condition)
$1.0 < PIj \leq 5.0$ → lightly polluted
$5.0 < PIj \leq 10$ → moderately polluted
$PIj > 10$ → heavily polluted

Figure 1. The location of Danau Seran Post-Mining

Figure 2. The location of Pumpung Post-Mining

Results
The concentrations of heavy metals measured at each observation station diverse, some are varied and some are not so much different concentrations.

Table 1. Data results of water sample measurements at

$$PI_i = \sqrt{\frac{M \quad R}{2}}$$

Author et al. (year)

Parameters	Unit	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
Fe	Mg/L	0.3	0.3	0.40	0.3	0.3	0.3
Mn	Mg/L	0.34	0.23	0.41	0.25	0.25	0.26
Zn	Mg/L	0.688	0.165	0.162	0.148	0.082	0.071
Pb	Mg/L	0.03	0.03	0.03	0.03	0.03	0.03
As	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Co	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Se	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cd	Mg/L	0.004	0.004	0.004	0.004	0.004	0.004
Cu	Mg/L	0.008	0.008	0.008	0.008	0.008	0.008
Hg	Mg/L	0.075	0.075	0.075	0.075	0.075	0.075
Ni	Mg/L	0.044	0.044	0.044	0.044	0.044	0.044
B	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cr Total	Mg/L	0.015	0.015	0.015	0.015	0.015	0.015

Source : Primary Data, 2022

Table 2. Data results of water sample measurements at Pumpung

Parameter	Unit	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
Fe	Mg/L	0.86	0.63	0.42	0.3	0.43	0.33
Mn	Mg/L	0.16	0.16	0.19	0.1	0,1	0.11
Zn	Mg/L	0.111	0.075	0.090	0,05	0.051	0.05
Pb	Mg/L	0.03	0.03	0.03	0.03	0.03	0.03
As	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Co	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Se	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cd	Mg/L	0.004	0.004	0.004	0.004	0.004	0.004
Cu	Mg/L	0.013	0.010	0.010	0.010	0.010	0.010
Hg	Mg/L	0.075	0.075	0.075	0.075	0.075	0.075
Ni	Mg/L	0.044	0.044	0.044	0.044	0.044	0.044
B	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cr Total	Mg/L	0.018	0.015	0.015	0.015	0.015	0.015

Source : Primary Data, 2022

After performing calculations with the PI equation, the following results are obtained:

Table 3. Pollution Index Calculation Results at Danau Seran

Pumpung	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
(Ci/Lij)R	1.28	0.94	1.06	0.92	1.00	1.02
(Ci/Lij)M	8.87	1.00	1.40	1.00	1.04	1.21
PI	4.481	0.686	0.878	0.681	0.724	0.789
Quality	Lightly	Meet	Meet Quality	Meet Quality	Meet Quality	Meet Quality
Status	Pollution	Quality Standards	Standards	Standards	Standards	Standards

Source : Processed primary data

Danau Seran	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
(Ci/Lij)R	1.62	0.91	1.10	0.96	0.96	1.00
(Ci/Lij)M	8.87	1.00	2.26	1.00	1.00	1.09
PI	4.508	0.686	1.255	0.693	0.694	0.736
Quality Status	Lightly	Meet Quality	Meet Quality	Standards	Lightly	Pollution

Meet Quality Standards

Discussion

Based on the results of the data above, it can be seen that the post-mining pit Danau Seran, Banjarbaru City, generally meets the Quality Standards for class 2 designation. This means that these waters could be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water to irrigate crops and for other uses that require the same quality of water as those uses. However, at station 1 and station 3, the Pollution Index (PI) results were obtained at 4.508 and 1.255, which means that these locations were indicated to be lightly polluted, so further management of the measured parameters was needed so that the water quality at that point could be appropriate. with the need for predetermined water quality standards (Widiatmaka, et al., 2010; Wikurendra, et al., 2022).

The development of Danau Seran tourism was originally intended to develop the region and create new growth in the area. Utilization of post-diamond mining land PT. Galuh Cempaka, among other things, was to create new public spaces, encourage the growth of small and medium enterprises, create new jobs, develop tourism objects, and open up regional sources of income. From various aspects of the utilization of Danau Seran, no review was carried out from the side of water quality. The problem of changing the landscape will further impact on the water quality of Seran Lake (Munir and Setyowati, 2017; Novianti *et al.*, 2017).

Numbers of rivers around Seran Lake were experiencing a lot of siltation caused by silt sedimentation from mining activities. This clearly causes the potential for flooding which can occur at any time, but from a micro perspective this can be overcome by improving the quality and performance of the inlet and outlet handles in the Galuh Cempaka Site, where Danau Seran was located on peat soil.

Commented [A.1]: You can enhance the paragraph by adding specific actions that can be taken in water quality management and monitoring, providing a clearer picture of the steps that can be taken to address the slight pollution at stations 1 and 3

Meet Quality Standards

Meet Quality Standards

In the post-mining waters in Pumpung, Banjarbaru City, it can be seen that these waters

Table 4. Pollution Index Calculation Results at Pumpung

generally meet the Quality Standards for class 2 designations where these waters can be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water for irrigating

Commented [A.2]: Added explanation for limits for quality standards entering class 2

crops and for other uses that require the same quality of water as those uses. However, at station 1, the results of the Pollution Index (PI) figure were 4.481, which means that the location was indicated to be lightly polluted, so further management of the measured parameters was needed so that the water quality at that point coud meet the needs of water quality standards established (Kirschke et al., 2020).

In contrast to the Danau Seran post-mining, the Pumpung area is a community's traditional post-diamond mining. Pumpung Village is famous for finding a diamond for the size of a chicken egg weighing 166.7 pieces, in the 30s years ago which was known as the Trisakti.

The diamond mining system in Pumpung Village uses a dumping system, namely a method of mining by stripping the surface soil and then continuing with excavation, but after mining was complete, the top soil layer was not returned to its original place. Physically, the condition of the former mining site was very bad, from large holes like lakes and surrounded by heaps of excavated earth like small irregular hills. Under these conditions, the utilization of the post-mining area as agricultural land was very difficult to manage. Returning the quality of former mining areas as agricultural land requires a very large investment, which was actually the responsibility of the miners (Barkatullah and Abdullah, 2016)

Mining activities that do not pay attention to environmental aspects from erosion and landslide hazards as loss of ground cover vegetation. Land clearing on a large scale causes a landscape (morphology and topography), namely a change in the shape of the slope. Stripping, stockpiling of overburden from diamond mining activities causes changes in drainage, river water discharge and surface quality when it rains (Andriawan, et al., 2021).

Based on water quality data for Danau Seran and Pumpung, several heavy metals such as Fe, Zn, and Hg had values that exceed the required water quality standards. Heavy metal pollution from mining activities can cause changes in the quality of the aquatic environment, one of which is post-mining land (Islam, et al., 2015) and affects the life of the biota in it (Barbieri et al., 2020; Fuoco and Giannarelli 2019; Kurz et al., 2013) . Continuous pollution can have an impact on biota and even cause death to impact the population (Kadim et al., 2022).

The heavy metal parameters that had the most influence on the Pollution Index results obtained include Fe, Zn and Hg, which can disturb the environment. Even though Fe and Zn are essential heavy metal groups, if they are present in excessive amounts they are toxic to living things (Febrina and Ayuna, 2015; Kamarati et al., 2018; Said and Yudo, 2021).

The presence of iron can be affected by acidic water conditions. Mining land of diamonds in Danau Seran and Pumpung were pyrite (FeS_2). The mineral pyrite (FeS_2), in post-coal mining land, is oxidized to sulfuric acid and can drastically reduce soil pH. Meanwhile carbonate ($Ca/MgCO_3$) which coats minerals and rocks tends to increase soil pH due to weathering and dissolving. In post-mining land where the carbonate is not weathered it causes a greater accumulation of pyrite, so that the pH can fall quickly (Erfandi, 2017; Hirfan, 2016; Supriyatna et al., 2013)

While the main role of zinc in waters is as a cofactor for two important enzymes for the development of phytoplankton, namely carbonic anhydrase and alkaline phosphatase. Apart from being essential, zinc can also be toxic and generally zinc is toxic when it is in the dissolved phase (Ali et al., 2018)

The presence of Hg as part of non-essential heavy metals will be toxic to organisms in the waters. High Hg levels, both in Danau Seran and Pumpung, would be toxic and the benefits for the aquatic organisms that live in them were not yet known. Metabolic processes in living bodies will be interrupted due to toxic forces that will work as a barrier to the work of enzymes in the body (Kadim et al., 2022; Said and Yudo, 2021; Sofarini et al., 2022).

Based on data on several heavy metals which were quite high in Danau Seran and Pumpung, it will have a further impact on the Pollution Index which was classified as lightly polluted at Stations 1 and 3. However, despite the problems found, Danau Seran and Pumpung still have considerable potential for developed. This of course has to go through several processes and stages, especially post-mining land reclamation.

Reclamation activities are the end of mining activities which are expected to return land to its original state, even if possible, to be better than conditions before mining. The ultimate goal of reclamation is to restore post-mining land to be safe, stable and not easily eroded so that, it can be utilized back (Hirfan, 2016). In general, the outline of the reclamation stages are top soil conservation, land management, sediment management and erosion control, planting cover crops, planting pioneer plants, and controlling heavy metals through the concepts of phytoremediation or bioremediation (Hendrychov´a et al., 2020; Hirfan, 2016) .

Conclusion

Commented [A.3]: describe the chemical mechanisms involved in the oxidation process of pyrite to sulfuric acid and its impact on soil pH. This will help readers who may not have a background in chemistry to better understand how heavy metal pollution such as iron can affect soil and water quality at mining sites.

The post-mining pits in Danau Seran and Pumpung, Banjarbaru City, have quite good water quality, most of which were at class 2 quality standards. These waters could be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water for irrigation. plantations and for other uses that require the same quality of water as that use. However, further management was needed to improve water quality at some points which still did not meet class 2 quality standards so that they were included in the lightly polluted category.

Acknowledgments

References

Absori, Absori, Aulia Vivi Yulianingrum, Khudzaifah Dimyati, Harun Harun, Arief Budiono, Hari Sutra Disemadi . 2021. "Environmental Health-Based Post-Coal Mine Policy in East Borneo." Open Access Macedonian Journal of Medical Sciences 9: 740–44.

Adibi, Nabiollah, Majid Ataee-Pour, and Mehdi Rahmanpour. 2015. "Integration of Sustainable Development Concepts in Open Pit Mine Design." Journal of Cleaner Production 108: 1037–49. http://dx.doi.org/10.1016/j.jclepro.2015.07.150.

Ali, Attarad, Abdul-rehman Phull, and Muhammad Zia. 2018. "Elemental Zinc to Zinc Nanoparticles : Is ZnO NPs Crucial for Life ? Synthesis , Toxicological , and Environmental Concerns." Nanotechnol Review 7(5): 413–41.

Andriawan, Feri, Muhammad Akib, and Agus Triono. 2021. "Pengendalian Kerusakan Lingkungan Akibat Aktivitas Pertambangan Di Kecamatan Pasir Sakti (Environmental Damage Control Due to Mining Activities in Pasir Sakti District)." Jurnal Ilmiah Hukum dan Hak Asasi Manusia 1(1): 1–10.

Asr, Elmira Tajvidi, Reza Kakaie, Mohammad Ataei, and Mohammad Reza Tavakoli Mohammadi. 2019. "A Review of Studies on Sustainable Development in Mining Life Cycle." Journal of Cleaner Production 229: 213–31. https://doi.org/10.1016/j.jclepro.2019.05.029.

Barbieri, Maria Vittoria et al. 2020. Environmental Pollution Jo Ur l P Re Of. Elsevier Ltd. https://doi.org/10.1016/j.envpol.2020.115813

Barkatullah, Abdul Halim, and Dadang Abdullah. 2016. "Tanggung Jawab Pemerintah Dalam Menjaga Kualitas Lingkungan Di Wilayah Penambangan Intan Tradisional Cempaka." Al'Adi VIII(3): 1–22.

Dinora, G.Q; Purnomo, A. 2013. "Penurunan Kandungan Zat Kapur Dalam Air Tanah Dengan Menggunakan Media Zeolit Alam Dan Karbon Aktif Menjadi Air Bersih." Jurnal Teknik Pomits 2(2): D78–82.

Dutu, Richard. 2016. "Challenges and Policies in Indonesia's Energy Sector." Energy Policy 98: 513–19. http://dx.doi.org/10.1016/j.enpol.2016.09.009

Erfandi, Deddy. 2017. "Pengelolaan Lansekap Lahan Bekas Tambang: Pemulihan Lahan Dengan Pemanfaatan Sumberdaya Lokal (In-Situ)." Jurnal Sumberdaya Lahan 11(2): 55–66.

Febrina, Leila, and Astrid Ayuna. 2015. "Studi Penurunan Kadar Besi (Fe) Dan Mangan (Mn) Dalam Air Tanah Menggunakan Saringan Keramik." Teknologi 7(1): 35–44.

Fuoco, Roger, and Stefania Giannarelli. 2019. "Integrity of Aquatic Ecosystems : An Overview of a Message from the South Pole on the Level of Persistent Organic Pollutants (POPs) ☆." Microchemical Journal 148(February): 230–39. https://doi.org/10.1016/j.microc.2019.04.076.

Goswami, Sribas. 2015. "Impact of Coal Mining on Environment." European Researcher 92(3): 185–96.

Haridjaja, Oteng, Wiwik Dwi Haryanti, and Rina Oktaviani. 2011. "Perencanaan Pengelolaan Sumberdaya Lahan Yang Terkena Dampak Penggunaan Lahan Untuk Penambangan Kapur." Jurnal Ilmu Pertanian Indonesia 16(1): 35–42.

Hendrychov´a, Mark´eta, Kamila Svobodova, and Martin Kabrna. 2020. "Mine Reclamation Planning and Management : Integrating Natural Habitats into Post-Mining Land Use." Resources Policy 69(September): 1–13.

Hirfan. 2016. "Strategi Reklamasi Lahan Pasca Tambang." Pena Teknik 1(1): 101–8.

Hudayana, Bambang, Suharko, and A. B. Widyanta. 2020. "Communal Violence as a Strategy for Negotiation: Community Responses to Nickel Mining Industry in Central Sulawesi, Indonesia." Extractive Industries and Society 7(4): 1547–56. https://doi.org/10.1016/j.exis.2020.08.012.

Islam, Saiful, Kawser Ahmed, and Mohammad Raknuzzaman. 2015. "Heavy Metal Pollution in Surface Water and Sediment : A Preliminary Assessment of an Urban River in a Developing Country." Ecological Indicators 48: 282–91. http://dx.doi.org/10.1016/j.ecolind.2014.08.016.

Kadim, Miftahul Khair et al. 2022. "Distribution of Heavy Metal (Pb, Cd and Hg) Concentrations in Sediment of Bone River, Gorontalo." Depik 11(3): 282–87.

Kadir Jaelani, Abdul, Reza Octavia Kusumaningtyas, and Asron Orsantinutsakul. 2022. "The Model of Mining Environment Restoration Regulation Based on Sustainable Development Goals." Legality : Jurnal Ilmiah Hukum 30(1): 131–46.

Kamarati, Kiamah Fathirizki A et al. 2018. "Kandungan Logam Berat Besi (Fe), Timbal (Pb) dan Mangan (Mn) pada Air Sungai Santan." Jurnal Penelitian Ekosistem Dipteropkarya 4(1): 49–56.

Kirschke, Sabrina et al. 2020. "Capacity Challenges in Water Quality Monitoring: Understanding the Role of Human Development." Environmental Monitoring and Assessment 192(5).

Kodir, Abdul, Djoko M. Hartono, Herman Haeruman, and Irdika Mansur. 2017. "Integrated Post Mining Landscape for Sustainable Land Use : A Case Study in South Sumatera, Indonesia." Sustainable Environment Research 27(4): 203–13. http://dx.doi.org/10.1016/j.serj.2017.03.003.

Kurz, Marie J et al. 2013. "Controls on Diel Metal Cycles in a Biologically Productive Carbonate-Dominated River." Chemical Geology 358: 61–74. http://dx.doi.org/10.1016/j.chemgeo.2013.08.042.

McCullough, Clint D., and Eddie J.B. van Etten. 2011. "Ecological Restoration of Novel Lake Districts: New Approaches for New Landscapes." Mine Water and the Environment 30(4): 312–19.

Munir, Misbakhul, and R.R.Dyah Nugrahaeni Setyowati. 2017. "Kajian Reklamasi Lahan Pasca Tambang Di Jambi, Bangka, Dan Kalimantan Selatan." KLOROFIL 1(1): 11–16.

Novianti, Yuniar Siska et al. 2017. "Kajian Kualitas Air Pada Danau Bekas Tambang Di Kota Banjarbaru Provinsi Kalimantan Selatan." Prosiding Seminar Nasional Riset Terapan 5662(November): 70–77.

Said, Nusa Idaman, and Satmoko Yudo. 2021. "Status Kualitas Air Di Kolam Bekas Tambang Batubara Tambang Stui, Kabupaten Tanah Laut, Kalimantan Selatan." Teknologi Lingkungan 22(1): 048–057.

Salomons, W. 1995. "Environmental Impact of Metals Derived from Mining Activities: Processes, Predictions, Prevention." Journal of Geochemical Exploration 52(1–2): 5–23.

Setiawan, Andi Arif, Dedik Budianta, Suheryanto Suheryanto, and Dwi Putro Priadi. 2018. "Review : Pollution Due to Coal Mining Activity and Its Impact on Environment." Sriwijaya Journal of Environment 3(1): 1–5.

Sofarini, Dini. 2011. "Karakteristik Fisik-Kimia Kualitas Air Pada Lahan Bekas Tambang Bahan Galian Golongan c Di Kecamatan Landasan Ulin Kota Banjarbaru." EnviroScienteae 7: 6–11.

Sofarini, Dini, Suhaili Asmawi, Rina Nur Hidayah, and Guinever Castle Angela Mangalik. 2022. "Heavy Metal Residue on Water, Biota and Sediment in Negara River." Russian Journal of Agricultural and Socio-economic Sciences 10(130): 101–8.

Supriyatna, Ateng, R.D Ramdani, and Dede Suhendar. 2013. "Korelasi Kandungan Besi Terlarut Terhadap Kelimpahan Phytoconois Sp Pada Perairan Situ Ciburuy Kabupaten Bandung Barat." Jurnal Sunan Gunung Djati VII(1): 1–18.

Tarras-Wahlberg, N. H. 2002. "Environmental Management of Small-Scale and Artisanal Mining: The Portovelo-Zaruma Goldmining Area, Southern Ecuador." Journal of Environmental Management 65(2): 165–79.

Widiatmaka, Suwarno, and Nandi Kusmaryandi. 2010. "Karakteristik Pedologi Dan Pengelolaan Revegetasi Lahan Bekas Tambang Nikel : Studi Kasus Lahan Bekas Tambang Nikel Pomalaa , Sulawesi Tenggara Pedological Characteristics And Revegetation Management Of Nickel Post Mining Land : Case Study Of Nickel Post." 12(2): 1–10.

Wikurendra, Edza Aria, Achmad Syafiuddin, Globila Nurika, and Alinea Dwi Elisanti. 2022. "Water Quality Analysis of Pucang River, Sidoarjo Regency to Control Water Pollution." Environmental Quality Management 32(1): 133–44.

Xu, Shanshan et al. 2021. "Effects of Vegetation Restoration on Accumulation and Translocation of Heavy Metals in Post-Mining Areas." Land Degradation and Development 32(5): 2000–2012.

Younger, Paul L. 2004. "Environmental Impacts of Coal Mining and Associated Wastes: A Geochemical Perspective." Geological Society Special Publication 236: 169–209.

Yunus, Muhammad; Prabowo, B.A. 2023. "Al-Azhar Islamic Law Review." Al-Azhar Islamic Law Review 5(1): 61–71.

3. Bukti Konfirmasi Submit Revisi Pertama, Respon kepada Reviewer, dan Artikel yang Diresubmit

(18 Sept 2023)

Editor Decision

Decision	Accept Submission 2023-09-23
Notify Editor	Editor/Author Email Record 2023-09-23
Editor Version	32909-111068-1-ED.DOCX 2023-07-29
Author Version	32909-115326-1-ED.DOCX 2023-09-18 DELETE
Upload Author Version	Choose File No file chosen Upload

DEPIK
Jurnal Ilmu-Ilmu Perairan, Pesisir dan Perikanan
Journal homepage: www.jurnal.usk.ac.id/depik

Study of water quality for post-mining extermination, Banjarbaru City

Dini Sofarini[1,*], Reza Agustian[2], Yunandar[1], Rina Nur Hidayah[1]

[1] Department of Aquatic Resource Management, Faculty of Fisheries and Marine, Universitas Lambung Mangkurat, Indonesia.
[2] Geoenviro Environmental Laboratory, Indonesia.

ABSTRACT

Banjarbaru City is one of the regencies/cities in South Kalimantan Province which continues to develop in various sectors, one of which is mining. Among the mining areas that left traces of voids in Banjarbaru include the Lake Seran quarry which was once a sand mining site, as well as the Pumpung quarry which was a diamond mining location. Remains of former mining excavations that are left for a long time will be filled with water which accumulates various substances remaining at the excavation site, especially heavy metals which in general are important parameters and affect water quality. This study aims to examine the quality of ex-mine water in Banjarbaru by focusing on analysis through the Pollution Index (IP) of heavy metal parameters in the waters of the research location. The results obtained are that the ex-mine pits in Lake Seran and Pumpung, Banjarbaru City, have quite good water quality, where most of them are at class 2 quality standards. However, further management is needed to improve water quality at some points that are still not meets class 2 quality standards so that it is included in the category of lightly polluted.

Introduction

Mining activities have a very important function in supporting economic activities in Indonesia, including South Kalimantan. Apart from contributing a sizable amount of foreign exchange, mining activities are also able to absorb a large number of workers and create centers of economic growth and new settlements.

In addition to providing great benefits, mining activities also cause problems in environmental management. Some of these problems include the occurrence of water pollution, land degradation, decreased biodiversity (Goswami, 2015; Salomons, 1995; Setiawan et al., 2018; Younger, 2004), land conflict (Dutu, 2016; Hudayana et al., 2020), and in certain cases there has been a breakdown of settling ponds and the drowning of several victims (people) in inactive post-mining pits filled with water called coal mine pit lakes or post-mining pits. (Yunus and Prabowo, 2023)

Mining activities have a great impact on the ecosystem around the mining site, one of which is the aquatic ecosystem (artificial lakes). Changes in water quality will definitely occur due to changes in the landscape, which means it will affect the life of living things in it (McCullough and van Etten, 2011; Sofarini, 2011)

In general, post-mining pits will fill with water and accumulate various parameters of heavy metals such as Pb, Hg, Cd, Fe and others (Wahlberg, 2002; Xu et al., 2021). The presence of these heavy metals will disrupt the stability of the ecosystem if not taken seriously. According to Dinora and Purnomo (2013), Fe is a type of heavy metal that can be found in almost all of the earth's surface in all geological layers and waters. In natural water systems and also in water treatment systems, iron compounds can vary depending on the pH of the water.

Post-mining land that has been damaged in its management must prioritize improving its

---

biophysical or ecological conditions, with the results

of the analysis in this study being post-mining land management based on sustainable development (Haridjaja *et al*., 2011; Kodir *et al*., 2017). The presence of post-mining pits that have not been closed or not closed indicates problems both from the aspect of scenarios for exploitation and operational activities for closing post-mining pits, weak instruments in mining environmental management, and the resulting environmental impacts (Adibi *et al*., 2015; Asr *et al*., 2019; Jaelani *et al*., 2022).

These various problems are an increasing challenge, considering the need for better environmental management while the number of post-mining is increasing (Absori et al., 2021). This study seeks to photograph the problems of post-mining pits and see opportunities for the utilization of post-mining pits from various aspects of utilization and regulatory needs. The results of this study are expected to be useful as a reference for formulating operational policies in the utilization of post-mining pits in mining activities in South Kalimantan

Materials and Methods
Location and time of research

This research was carried out for 4 months from June to October 2022. The research was carried out in ex-mining pits in Lake Seran and Pumpung which are located in Banjarbaru City, South Kalimantan Province (Figure 1 and Figure 2). Determining the location of water sampling was carried out by purposive sampling. The method used is explorative quantitative

Data collection procedure

Analysis of water quality parameters refers to the Indonesian national standard (SNI) according to SNI 6989.59:2008 and 6989.57:2008 as much as 5 liters using a water sampler and sampling container. Then the samples were brought to the laboratory for analysis of the physical and chemical parameters of the water. The instrument used has previously been tested for calibration

Data analysis

The data obtained was then analyzed using the Pollution Index (PI) method according to the Decree of the State Minister for the Environment Number 115 of 2003 concerning Guidelines for Determining Water Quality Status with class 2 quality standard criteria. The PI calculation is carried out based on the following equation:

$$PI_j = \sqrt{\frac{(C_i/L_{ij})^2_M + (C_i/L_{ij})^2_R}{2}}$$

Information :

PIj = Pollution Index for designation (j)
Ci = Concentration of water quality parameters

(
i
)
o
b
t
a
i
n
e
d
f
r
o
m
t
h
e
a
n
a
l
y
s
i
s
r
e
s
u
l
t
s
w
a
t
e
r
s
a
m
p
l
e
a
t
a
l
o
c
a
t
i
o
n
t

Lij = Concentration of water quality parameters listed in the Quality Standards Water Designation (j)

Ci/Lij)M = maxium value of Ci/Lij
(Ci/Lij)R = average value of Ci/Lij

The results of the calculations obtained will be interpreted with the following evaluation:

$0 \leq PIj \leq 1.0 \rightarrow$ meets the quality standard (good condition)
$1.0 < PIj \leq 5.0 \rightarrow$ lightly polluted
$5.0 < PIj \leq 10 \rightarrow$ moderately polluted
$PIj > 10 \qquad \rightarrow$ heavily polluted

Figure 1. The location of Danau Seran Post-Mining

Figure 2. The location of Pumpung Post-Mining

Results
The concentrations of heavy metals measured at each observation station diverse, some are varied and some are not so much different concentrations.

Table 1. Data results of water sample measurements at Danau Seran

3

Parameters	Unit	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
Fe	Mg/L	0.3	0.3	0.40	0.3	0.3	0.3
Mn	Mg/L	0.34	0.23	0.41	0.25	0.25	0.26
Zn	Mg/L	0.688	0.165	0.162	0.148	0.082	0.071
Pb	Mg/L	0.03	0.03	0.03	0.03	0.03	0.03
As	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Co	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Se	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cd	Mg/L	0.004	0.004	0.004	0.004	0.004	0.004
Cu	Mg/L	0.008	0.008	0.008	0.008	0.008	0.008
Hg	Mg/L	0.075	0.075	0.075	0.075	0.075	0.075
Ni	Mg/L	0.044	0.044	0.044	0.044	0.044	0.044
B	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cr Total	Mg/L	0.015	0.015	0.015	0.015	0.015	0.015

Source : Primary Data, 2022

Table 2. Data results of water sample measurements at Pumpung

Parameter	Unit	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
Fe	Mg/L	0.86	0.63	0.42	0.3	0.43	0.33
Mn	Mg/L	0.16	0.16	0.19	0.1	0,1	0.11
Zn	Mg/L	0.111	0.075	0.090	0,05	0.051	0.05
Pb	Mg/L	0.03	0.03	0.03	0.03	0.03	0.03
As	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Co	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Se	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cd	Mg/L	0.004	0.004	0.004	0.004	0.004	0.004
Cu	Mg/L	0.013	0.010	0.010	0.010	0.010	0.010
Hg	Mg/L	0.075	0.075	0.075	0.075	0.075	0.075
Ni	Mg/L	0.044	0.044	0.044	0.044	0.044	0.044
B	Mg/L	0.001	0.001	0.001	0.001	0.001	0.001
Cr Total	Mg/L	0.018	0.015	0.015	0.015	0.015	0.015

Source : Primary Data, 2022

After performing calculations with the PI equation, the following results are obtained:

Table 3. Pollution Index Calculation Results at Danau Seran

Danau Seran	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
(Ci/Lij)R	1.62	0.91	1.10	0.96	0.96	1.00
(Ci/Lij)M	8.87	1.00	2.26	1.00	1.00	1.09
Pi	4.508	0.676	1.255	0.693	0.694	0.736
Quality Status	Lightly Pollution	Meet Quality Standards	Lightly Pollution	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards

Source : Processed primary data

Pumpung	ST 1	ST 2	ST 3	ST 4	ST 5	ST 6
(Ci/Lij)R	1.28	0.94	1.06	0.92	1.00	1.02
(Ci/Lij)M	8.87	1.00	1.40	1.00	1.04	1.21
Pi	4.481	0.686	0.878	0.681	0.724	0.789
Quality Status	Lightly Pollution	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards	Meet Quality Standards

Source : Processed primary data

Discussion

Based on the results of the data above, it can be seen that the post-mining pit Danau Seran, Banjarbaru City, generally meets the Quality Standards for class 2 designation. This means that these waters could be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water to irrigate crops and for other uses that require the same quality of water as those uses. However, at station 1 and station 3, the Pollution Index (PI) results were obtained at 4.508 and 1.255, which means that these locations were indicated to be lightly polluted, so further management of the measured parameters was needed so that the water quality at that point could be appropriate. with the need for predetermined water quality standards (Widiatmaka, et al., 2010; Wikurendra, et al., 2022).

> **Commented [A.1]:** You can enhance the paragraph by adding specific actions that can be taken in water quality management and monitoring, providing a clearer picture of the steps that can be taken to address the slight pollution at stations 1 and 3

Several specific actions can be taken to overcome light pollution conditions at Stations 1 and 3. The application of the phytoremediation concept can be one of the treatment solutions. Phytoremediation is one method with an environmentally friendly concept. This technique can be applied to overcome light pollution through the biological process of breaking down pollutants. This technology has disadvantages in terms of a slow process and the need to select the right type of plant to reduce the types of heavy metals that pollute waters. The phytoextraction process is one of the important processes in the phytoremediation concept in reducing heavy metals and other pollutants from water (Bhat, et al., 2019; Mangkoedihardjo 2007; Milić et al., 2012)

> **Commented [KK2]:** The revision

The development of Danau Seran tourism was originally intended to develop the region and create new growth in the area. Utilization of post-diamond mining land PT. Galuh Cempaka, among other things, was to create new public spaces, encourage the growth of small and medium enterprises, create new jobs, develop tourism objects, and open up

Table 4. Pollution Index Calculation Results at Pumpung

regional sources of income. From various aspects of the utilization of Danau Seran, no review was carried out from the side of water quality. The problem of changing the landscape will further impact on the

water quality of Seran Lake (Munir and Setyowati, 2017; Novianti *et al*., 2017).

Numbers of rivers around Seran Lake were experiencing a lot of siltation caused by silt sedimentation from mining activities. This clearly causes the potential for flooding which can occur at any time, but from a micro perspective this can be overcome by improving the quality and performance of the inlet and outlet handles in the Galuh Cempaka Site, where Danau Seran was located on peat soil.

In the post-mining waters in Pumpung, Banjarbaru City, it can be seen that these waters

generally meet the Quality Standards for class 2 designations. This is stated in the data in Table 2, where all heavy metals in post-mining waters of Pumpung (Fe, Mn, Zn, Pb, As, Co, Se, Cd, Cu, Hg, Ni, B and Cr Total) do not exceed the required values PP No. 22 of 2021 water quality standards for lake waters. Quality Standards for class 2 designation state that these waters can be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water for irrigating crops and for other uses that require the same quality of water as those uses (Peraturan Pemerintah RI, 2021). However, at station 1, the results of the Pollution Index (PI) figure were 4.481, which means that the location was indicated to be lightly polluted, so further management of the measured parameters was needed so that the water quality at that point coud meet the needs of water quality standards established (Kirschke *et al*., 2020).

In contrast to the Danau Seran post-mining, the Pumpung area is a community's traditional post-diamond mining. Pumpung Village is famous for finding a diamond for the size of a chicken egg weighing 166.7 pieces, in the 30s years ago which was known as the Trisakti.

The diamond mining system in Pumpung Village uses a dumping system, namely a method of mining by stripping the surface soil and then continuing with excavation, but after mining was complete, the top soil layer was not returned to its original place. Physically, the condition of the former mining site was very bad, from large holes like lakes and surrounded by heaps of excavated earth like small irregular hills. Under these conditions, the utilization of the post-mining area as agricultural land was very difficult to manage. Returning the quality of former mining areas as agricultural land requires a very large investment, which was actually the responsibility of the miners (Barkatullah and Abdullah, 2016)

Mining activities that do not pay attention to environmental aspects from erosion and landslide

clearing on a large scale causes a landscape (morphology and topography), namely a change in the shape of the slope. Stripping, stockpiling of overburden from diamond mining activities causes changes in drainage, river water discharge and surface quality when it rains (Andriawan, *et al*., 2021).

Based on water quality data for Danau Seran and Pumpung, several heavy metals such as Fe, Zn, and Hg had values that exceed the required water quality standards. Heavy metal pollution from mining activities can cause changes in the quality of the aquatic environment, one of which is post-mining

land (Islam, *et al*., 2015) and affects the life of the biota in it (Barbieri *et al*., 2020; Fuoco and Giannarelli 2019; Kurz *et al*., 2013) . Continuous pollution can hazards as loss of ground cover vegetation. Land

Commented [A.3]: Added explanation for limits for quality standards entering class 2

have an impact on biota and even caused death to impact the population (K

The heavy metal parameters that had the most influence on the Pollution Index results obtained include Fe, Zn and Hg, which can disturb the environment. Even though Fe and Zn are essential heavy metal groups, if they are present in excessive amounts they are toxic to living things (Febrina and Ayuna, 2015; Kamarati *et al*., 2018; Said and Yudo, 2021).

The presence of iron can be affected by acidic water conditions. Mining land of diamonds in Danau Seran and Pumpung were pyrite (FeS_2). The mineral pyrite (FeS_2), in post-coal mining land, is oxidized to sulfuric acid and can drastically reduce soil pH. Meanwhile carbonate ($Ca/MgCO_3$) which coats minerals and rocks tends to increase soil pH due to weathering and dissolving. In post-mining land where the carbonate is not weathered it causes a greater accumulation of pyrite, so that the pH can fall quickly (Erfandi, 2017; Hirfan, 2016; Supriyatna *et al*., 2013)

Pyrite oxidation occurs due to the pyrite layer being exposed to oxygen caused by falling groundwater levels or drought. Falling groundwater levels can cause cracks to appear on the soil surface due to dryness, root scars or excessive drainage so that oxygen can enter the soil and can cause the pyrite layer to oxidize (Ratmini, 2018). Pyrite oxidation caused by oxygen as an oxidizing agent is less dangerous compared to oxidation caused by Fe^{3+}. This is in accordance with the pyrite oxidation reaction where the oxidation caused by oxygen only produces 2 mol of H^+ ions, while the oxidation of pyrite caused by Fe^{3+} produces 16 mol of H^+ ions. In soil that has undergone pyrite oxidation, pale yellow jarosite rust will be found in the cross-section of the soil and is often referred to as clay paint or in standing water which is toxic (Sandrawati et al.,

Commented [KK4]: The revision

Commented [A.5]: describe the chemical mechanisms involved in the oxidation process of pyrite to sulfuric acid and its impact on soil pH. This will help readers who may not have a background in chemistry to better understand how heavy metal pollution such as iron can affect soil and water quality at mining sites.

2019). Pyrite oxidation occurs when pyrite comes into contact with oxidizing agents, namely oxygen (O_2), Fe^{3+}, and oxidizing organisms which can accelerate the pyrite oxidation process (Lee et al., 2011).

While the main role of zinc in waters is as a cofactor for two important enzymes for the development of phytoplankton, namely carbonic anhydrase and alkaline phosphatase. Apart from being essential, zinc can also be toxic and generally zinc is toxic when it is in the dissolved phase (Ali *et al.*, 2018)

The presence of Hg as part of non-essential heavy metals will be toxic to organisms in the waters. High Hg levels, both in Danau Seran and Pumpung, would be toxic and the benefits for the aquatic organisms that live in them were not yet known. Metabolic processes in living bodies will be interrupted due to toxic forces that will work as a barrier to the work of enzymes in the body (Kadim *et al.*, 2022; Said and Yudo, 2021; Sofarini *et al.*, 2022).

Based on data on several heavy metals which were quite high in Danau Seran and Pumpung, it will have a further impact on the Pollution Index which was classified as lightly polluted at Stations 1 and 3. However, despite the problems found, Danau Seran and Pumpung still have considerable potential for developed. This of course has to go through several processes and stages, especially post-mining land reclamation.

Reclamation activities are the end of mining activities which are expected to return land to its original state, even if possible, to be better than conditions before mining. The ultimate goal of reclamation is to restore post-mining land to be safe, stable and not easily eroded so that, it can be utilized back (Hirfan, 2016). In general, the outline of the reclamation stages are top soil conservation, land management, sediment management and erosion control, planting cover crops, planting pioneer plants, and controlling heavy metals through the concepts of phytoremediation or bioremediation (Hendrychov´a et al., 2020; Hirfan, 2016) .

Conclusion

The post-mining pits in Danau Seran and Pumpung, Banjarbaru City, have quite good water quality, most of which were at class 2 quality standards. These waters could be used for water recreation infrastructure/facilities, freshwater fish farming, animal husbandry, water for irrigation. plantations and for other uses that require the same quality of water as that use. However, further management was needed to improve water quality at some points which still did not meet class 2 quality standards so that they were included in the lightly polluted category.

Acknowledgments

References

Absori, Absori, Aulia Vivi Yulianingrum, Khudzaifah Dimyati, Harun Harun, Arief Budiono, Hari Sutra Disemadi . 2021. "Environmental Health-Based Post-Coal Mine Policy in East Borneo." Open Access Macedonian Journal of Medical Sciences 9: 740–44.

Adibi, Nabiollah, Majid Ataee-Pour, and Mehdi Rahmanpour. 2015. "Integration of Sustainable Development Concepts in Open Pit Mine Design." Journal of Cleaner Production 108: 1037–49. http://dx.doi.org/10.1016/j.jclepro.2015.07.150.

Ali, Attarad, Abdul-rehman Phull, and Muhammad Zia. 2018. "Elemental Zinc to Zinc Nanoparticles : Is ZnO NPs Crucial for Life ? Synthesis , Toxicological , and Environmental Concerns." Nanotechnol Review 7(5): 413–41.

Andriawan, Feri, Muhammad Akib, and Agus Triono. 2021. "Pengendalian Kerusakan Lingkungan Akibat Aktivitas Pertambangan Di Kecamatan Pasir Sakti (Environmental Damage Control Due to Mining Activities in Pasir Sakti District)." Jurnal Ilmiah Hukum dan Hak Asasi Manusia 1(1): 1–10.

Asr, Elmira Tajvidi, Reza Kakaie, Mohammad Ataei, and Mohammad Reza Tavakoli Mohammadi. 2019. "A Review of Studies on Sustainable Development in Mining Life Cycle." Journal of Cleaner Production 229: 213–31. https://doi.org/10.1016/j.jclepro.2019.05.029.

Barbieri, Maria Vittoria et al. 2020. Environmental Pollution Jo Ur l P Re Of. Elsevier Ltd. https://doi.org/10.1016/j.envpol.2020.115813

Barkatullah, Abdul Halim, and Dadang Abdullah. 2016. "Tanggung Jawab Pemerintah Dalam Menjaga Kualitas Lingkungan Di Wilayah Penambangan Intan Tradisional Cempaka." Al'Adi VIII(3): 1–22.

Bhat, Mohd Muzamil, R N Shukla, and M Yunus. 2019. "Urban Pond Ecosystems : Preservation and Management Through Phytoremediation." *Fresh Water Pollution Dynamics and Remediation*: 263–91.

Dinora, G.Q; Purnomo, A. 2013. "Penurunan Kandungan Zat Kapur Dalam Air Tanah Dengan Menggunakan Media Zeolit Alam Dan Karbon Aktif Menjadi Air Bersih." Jurnal Teknik Pomits 2(2): D78–82.

Dutu, Richard. 2016. "Challenges and Policies in Indonesia's Energy Sector." Energy Policy 98: 513–19. http://dx.doi.org/10.1016/j.enpol.2016.09.009

Erfandi, Deddy. 2017. "Pengelolaan Lansekap Lahan Bekas Tambang: Pemulihan Lahan Dengan Pemanfaatan Sumberdaya Lokal (In-Situ)." Jurnal Sumberdaya Lahan 11(2): 55–66.

Febrina, Leila, and Astrid Ayuna. 2015. "Studi Penurunan Kadar Besi (Fe) Dan Mangan (Mn) Dalam Air Tanah Menggunakan Saringan Keramik." Teknologi 7(1): 35–44.

Fuoco, Roger, and Stefania Giannarelli. 2019. "Integrity of Aquatic Ecosystems : An Overview of a Message from the South Pole on the Level of Persistent Organic Pollutants (POPs) ☆." Microchemical Journal 148(February): 230–39. https://doi.org/10.1016/j.microc.2019.04.076.

Goswami, Sribas. 2015. "Impact of Coal Mining on Environment." European Researcher 92(3): 185–96.

Commented [KK6]: The revision

Haridjaja, Oteng, Wiwik Dwi Haryanti, and Rina Oktaviani. 2011. "Perencanaan Pengelolaan Sumberdaya Lahan Yang Terkena Dampak Penggunaan Lahan Untuk Penambangan Kapur." Jurnal Ilmu Pertanian Indonesia 16(1): 35–42.

Hendrychov´a, Mark´eta, Kamila Svobodova, and Martin Kabrna. 2020. "Mine Reclamation Planning and Management : Integrating Natural Habitats into Post-Mining Land Use." Resources Policy 69(September): 1–13.

Hirfan. 2016. "Strategi Reklamasi Lahan Pasca Tambang." Pena Teknik 1(1): 101–8.

Hudayana, Bambang, Suharko, and A. B. Widyanta. 2020. "Communal Violence as a Strategy for Negotiation: Community Responses to Nickel Mining Industry in Central Sulawesi, Indonesia." Extractive Industries and Society 7(4): 1547–56. https://doi.org/10.1016/j.exis.2020.08.012.

Islam, Saiful, Kawser Ahmed, and Mohammad Raknuzzaman. 2015. "Heavy Metal Pollution in Surface Water and Sediment : A Preliminary Assessment of an Urban River in a Developing Country." Ecological Indicators 48: 282–91. http://dx.doi.org/10.1016/j.ecolind.2014.08.016.

Kadim, Miftahul Khair et al. 2022. "Distribution of Heavy Metal (Pb, Cd and Hg) Concentrations in Sediment of Bone River, Gorontalo." Depik 11(3): 282–87.

Kadir Jaelani, Abdul, Reza Octavia Kusumaningtyas, and Asron Orsantinutsakul. 2022. "The Model of Mining Environment Restoration Regulation Based on Sustainable Development Goals." Legality : Jurnal Ilmiah Hukum 30(1): 131–46.

Kamarati, Kiamah Fathirizki A et al. 2018. "Kandungan Logam Berat Besi (Fe), Timbal (Pb) dan Mangan (Mn) pada Air Sungai Santan." Jurnal Penelitian Ekosistem Dipteropkarya 4(1): 49–56.

Kirschke, Sabrina et al. 2020. "Capacity Challenges in Water Quality Monitoring: Understanding the Role of Human Development." Environmental Monitoring and Assessment 192(5).

Kodir, Abdul, Djoko M. Hartono, Herman Haeruman, and Irdika Mansur. 2017. "Integrated Post Mining Landscape for Sustainable Land Use: A Case Study in South Sumatera, Indonesia." Sustainable Environment Research 27(4): 203–13. http://dx.doi.org/10.1016/j.serj.2017.03.003.

Kurz, Marie J et al. 2013. "Controls on Diel Metal Cycles in a Biologically Productive Carbonate-Dominated River." Chemical Geology 358: 61–74. http://dx.doi.org/10.1016/j.chemgeo.2013.08.042.

Lee, Jin Soo, Chul Min Chon, and Jae Gon Kim. 2011. "Suppression of Pyrite Oxidation by Formation of Iron Hydroxide and Fe (III) - Silicate Complex under Highly Oxidizing Condition Suppression of Pyrite Oxidation by Formation of Iron Hydroxide and Fe (III) -Silicate Complex under Highly Oxidizing Condit." Korean J. Soil Sci. Fert 2: 297–302.

Mangkoedihardjo, Sarwoko. 2007. "Phytotechnology Integrity in Environmental Sanitation for Sustainable Development." Journal of Applied Sciences Research 3(10): 1037–44.

McCullough, Clint D., and Eddie J.B. van Etten. 2011. "Ecological Restoration of Novel Lake Districts: New Approaches for New Landscapes." Mine Water and the Environment 30(4): 312–19.

Milić, Dubravka et al. 2012. "Heavy Metal Content in Halophytic Plants from Inland and Maritime Saline Areas." Central European Journal of Biology 7(2): 307–17.

Munir, Misbakhul, and R.R.Dyah Nugrahaeni Setyowati. 2017. "Kajian Reklamasi Lahan Pasca Tambang Di Jambi, Bangka, Dan Kalimantan Selatan." KLOROFIL 1(1): 11–16.

Novianti, Yuniar Siska et al. 2017. "Kajian Kualitas Air Pada Danau Bekas Tambang Di Kota Banjarbaru Provinsi Kalimantan Selatan." Prosiding Seminar Nasional Riset Terapan 5662(November): 70–77.

Peraturan Pemerintah RI, No 22 Th 2021. 2021. 1 Sekretariat Negara Republik Indonesia Peraturan Pemerintah No 22 Tahun 2021 Tentang Penyelenggaraan Perlindungan Dan Pengelolaan Lingkungan Hidup. http://www.jdih.setjen.kemendagri.go.id/.

Ratmini, Niluh Putu Sri. 2018. "Kajian Provitas Lahan Sulfat Masam Sumatera Selatan : Studi Kasus Desa Mulya Sari Kecamatan Tanjunglago." Agroecotenia 1(1): 52–62.

Sandrawati, Apong, Pujawati Suryatmana, Ikrar Nusantara Putra, and Nadia N Kamaluddin. 2019. "Soilrens." 17(1): 38–44.

Said, Nusa Idaman, and Satmoko Yudo. 2021. "Status Kualitas Air Di Kolam Bekas Tambang Batubara Tambang Stui, Kabupaten Tanah Laut, Kalimantan Selatan." Teknologi Lingkungan 22(1): 048–057.

Salomons, W. 1995. "Environmental Impact of Metals Derived from Mining Activities: Processes, Predictions, Prevention." Journal of Geochemical Exploration 52(1–2): 5–23.

Setiawan, Andi Arif, Dedik Budianta, Suheryanto Suheryanto, and Dwi Putro Priadi. 2018. "Review : Pollution Due to Coal Mining Activity and Its Impact on Environment." Sriwijaya Journal of Environment 3(1): 1–5.

Sofarini, Dini. 2011. "Karakteristik Fisik-Kimia Kualitas Air Pada Lahan Bekas Tambang Bahan Galian Golongan c Di Kecamatan Landasan Ulin Kota Banjarbaru." EnviroScienteae 7: 6–11.

Sofarini, Dini, Suhaili Asmawi, Rina Nur Hidayah, and Guinever Castle Angela Mangalik. 2022. "Heavy Metal Residue on Water, Biota and Sediment in Negara River." Russian Journal of Agricultural and Socio-economic Sciences 10(130): 101–8.

Supriyatna, Ateng, R.D Ramdani, and Dede Suhendar. 2013. "Korelasi Kandungan Besi Terlarut Terhadap Kelimpahan Phytoconois Sp Pada Perairan Situ Ciburuy Kabupaten Bandung Barat." Jurnal Sunan Gunung Djati VII(1): 1–18.

Tarras-Wahlberg, N. H. 2002. "Environmental Management of Small-Scale and Artisanal Mining: The Portovelo-Zaruma Goldmining Area, Southern Ecuador." Journal of Environmental Management 65(2): 165–79.

Widiatmaka, Suwarno, and Nandi Kusmaryandi. 2010. "Karakteristik Pedologi Dan Pengelolaan Revegetasi Lahan Bekas Tambang Nikel : Studi Kasus Lahan Bekas Tambang Nikel Pomalaa , Sulawesi Tenggara Pedological Characteristics And Revegetation Management Of Nickel Post Mining Land : Case Study Of Nickel Post." 12(2): 1–10.

Wikurendra, Edza Aria, Achmad Syafiuddin, Globila Nurika, and Alinea Dwi Elisanti. 2022. "Water Quality Analysis of Pucang River, Sidoarjo Regency to Control Water Pollution." Environmental Quality Management 32(1): 133–44.

Xu, Shanshan et al. 2021. "Effects of Vegetation Restoration on Accumulation and Translocation of Heavy Metals in Post-Mining Areas." Land Degradation and Development 32(5): 2000–2012.

Younger, Paul L. 2004. "Environmental Impacts of Coal Mining and Associated Wastes: A Geochemical Perspective." Geological Society Special Publication 236: 169–209.

Yunus, Muhammad; Prabowo, B.A. 2023. "Al-Azhar Islamic Law Review." Al-Azhar Islamic Law Review 5(1): 61–71.

4. Bukti Konfirmasi Artikel Accepted
(23 Sept 2023)

Layout

Layout Editor	None			
Layout Version	REQUEST	UNDERWAY	COMPLETE	VIEWS
None	—	—	—	
Galley Format	FILE			
1.　PDF　VIEW PROOF	51890.13333-1-PB.PDF　2024-01-03			8
Supplementary Files	FILE			
	None			

Layout Comments　No Comments

Proofreading

Proofreader	None		
REVIEW METADATA			
	REQUEST	UNDERWAY	COMPLETE
1.　Author	—	—	
2.　Proofreader	—	—	—
3.　Layout Editor	—	—	—

Proofreading Corrections　No Comments　PROOFING INSTRUCTIONS

5. Bukti Konfirmasi Artikel Published Online
(27 Des 2023)

✎ Compose

📁 Inbox   2,347
☆ Starred
① Snoozed
▷ Sent
🗋 Drafts   35
⌄ More

Labels   +

←   📁 ⊙ 🗑   🖻 ① ⊘   🗐 ▷ ⋮   1 of xx   ‹   ›

Decision on your paper submitted to Depik Jurnal Ilmu-Ilmu Perairan, Pesisir dan Kelautan

nurfadli@buak.ac.id nurfadli@buak.ac.id
to me, others, fulindepik? ⌄   ▦ Dec 27 2020, 7:03 AM   ☆   ↩   ⋮

Dear authors,

We have reached a decision regarding your submission to *Depik Jurnal Ilmu-Ilmu Perairan, Pesisir dan Kelautan*.

Manuscript Title: **Study of water quality for post-mining extermination, Banjarbaru City**

Our decision is to: Accept the submission

Before we proceed with the publication of your article, please complete the arranged payment of your article processing charge **IDR 1.500.000,00 (One million five hundred thousand rupiahs)** in 3 days by Bank transfer to:

ACCOUNT NAME: **DEPIK** JURNAL
ACCOUNT NUMBER: 7100072807
BENEFICIARY BANK: Bank Syariah Indonesia KCP Aceh Darussalam

P: 1. **Please fill out the publication ethics and malpractices statement of author's form (attached).**
       2. **Send the remittance receipt or payment screenshot, and name of the remitter to this email.**

If you have any questions, please do not hesitate to contact us

Kind regards,

Managing editor

---

2 Attachments · Scanned by Gmail ⓘ   ⬇ 🖶

📄 Letter of Accepta...   🖼 Etika penerbitan...

---

dini asfarini dini.asfarini@buak.ac.id
to nurfadli@buak.ac.id ⌄   ▦ Dec 29 2020, 3:27 PM   ☆   ↩   ⋮

Dear Editors
Here I sent the publication ethics and malpractices statement of author's
form and payment screenshot from me.. Dini Asfarini
Kind Regards,
Dini Asfarini

---

2 Attachments · Scanned by Gmail ⓘ   ⬇ 🖶

🖼 BSI...   🖼 Etika penerbitan...

(↩ Reply)   (↪ Forward)

Status

Submission Metadata

AUTHORS

Name	Dini Sofarini
Affiliation	Fakultas Perikanan dan Kelautan Universitas Lambung Mangkurat Banjarmasin
Country	Indonesia
Bio Statement	Department of Aquatic Resources Management
Principal contact for editorial correspondence.	
Name	Reza Agustian
Affiliation	JST Consultant
Country	—
Bio Statement	Geoservices Environmental Laboratory
Name	Yunandar Yunandar
Affiliation	Fakultas Perikanan dan Kelautan Universitas Lambung Mangkurat Banjarmasin
Country	—
Bio Statement	Department of Aquatic Resources Management
Name	Rina Nur Hidayah
Affiliation	Fakultas Perikanan dan Kelautan Universitas Lambung Mangkurat Banjarmasin
Country	—
Bio Statement	Department of Aquatic Resources Management

TITLE AND ABSTRACT

Title	Study of water quality for post-mining contamination, Banjarbaru City

Abstract

Banjarbaru City is one of the regencies/cities in South Kalimantan Province which continues to develop in various sectors, one of which is mining. Among the mining areas that left traces of voids in Banjarbaru include the Lake Seran quarry which was once a sand mining site, as well as the Pumpung quarry which was a diamond mining location. Remains of former mining excavations that are left for a long time will be filled with water which accumulates various substances remaining at the excavation site, especially heavy metals which in general are important parameters and affect water quality. This study aims to examine the quality of ex-mine water in Banjarbaru by focusing on analysis through the Pollution Index (PI) of heavy metal parameters in the waters of the research location. The results obtained are that the ex-mine pits in Lake Seran and Pumpung, Banjarbaru City, have quite good water quality, where most of them are at class 2 quality standards. However, further management is needed to improve water quality at some points that are still not meets class 2 quality standards so that it is included in the category of lightly polluted.

Keywords

Mining

Heavy Metals

Water Quality

Pollution Index

INDEXING

Language	en